


<p>PHONE : 592-261-2269 FAX : 592-261-2279 AFS : SYCJYOYX EMAIL : aisguyana@gcaa-gy.org</p>	 <p>AERONAUTICAL INFORMATION SERVICE Control Tower Complex, Timehri EAST BANK DEMERARA GUYANA</p>	<p>AIC B13/16 PINK 23 JUNE 2016</p>
<p><i><u>This AIC replaces AIC B02/08</u></i></p> <p style="text-align: center;"><u>OCCURRENCE OF WIND SHEAR</u></p> <p>Consequent to the conclusion of ICAO SAM 38/88 ATS/MET Informal Meeting, Lima, September 1988, contracting States of the Sam Region are required to launch a statistical study on the occurrence of wind shear at their aerodromes.</p> <p>Pilots and aircraft operators are requested to report the experience of this phenomenon to ATC when operating into Cheddi Jagan International Airport and Eugene F. Correia International. These reports will be summarised and forwarded to ICAO for further study.</p>		