



PHONE : 592-261-2269
 FAX : 592-261-2279
 AFS : SYCJYOYX
 EMAIL : aisguyana@gcaa-gy.org

AERONAUTICAL INFORMATION SERVICE
 CONTROL TOWER COMPLEX,
 TIMEHRI EAST BANK DEMERARA
 GUYANA

AIC

A03/17

PINK

23 FEBRUARY 2017

Temporary Obstacle In The Obstacle Free Zone Of Eugene F. Correia International Airport

The airport perimeter fence infringes on the runway strip to the left of runway 07. The fence is located one hundred and thirty (130) feet from the centerline of the runway and is ten (10) feet in height. The fence starting point is approximately eight hundred and fifty (850) feet from threshold of runway 07 and runs parallel to the runway for seven hundred and fifty (750) feet.

Please see diagram below.

